



LTL-X- Mounting rails for rain measurements

In order to move the measurement field outside the horizontal base cover (as shown in LTL-XL User Manual on figure 3, page Error! Bookmark not defined.) the two wet night rails should be mounted.



You will find two wet night rails in the carrying case. Be aware of that there is a left and a right one.



Bushing for the wet night rail

Mount the wet night rails by insert the rails into the bushing underneath the LTL-X



Fasten the wet night rails in the lid with the screws delivered with the rails. Make sure that the LTL-X is resting on the rails before lightening the screws.



We help ideas meet the real world



The Wet night rails are now ready for use. After use dismount the wet night feet by reversing above operations.